



11/21/2017

New Safety Recall Advanced Communication – T7311212017

FCA US LLC (FCA US) has announced a safety recall on certain 2018 model year (MP) Jeep Compass vehicles.

Some of the above vehicles may experience loose Passenger Airbag (PAB) inflator mounting nuts in the PAB module assembly. Inflator mounting nuts outside of the cushion assembly can become potential projectiles during PAB deployment. Inflator mounting nuts inside of the cushion assembly can potentially strike an occupant through the cushion fabric. Either of these failure modes may result in occupant injury during a crash that requires PAB deployment.

FCA US will conduct a voluntary safety recall to replace the PAB module assemblies. The remedy for this condition is not currently available.

VINs identified as being involved in this campaign are currently live and searchable.

IMPORTANT NOTE: Some of the involved vehicles may be in dealer new vehicle inventory. Federal law requires you to complete this recall service on these vehicles before retail delivery.

Dealers will be notified of the launch of this safety recall by way of established communication methods. This recall is estimated to launch in the 1st Quarter of 2018.

We ask that you please take the time to ensure that your personnel are aware of this communication and are prepared to execute a customer friendly process for inquiries regarding involved vehicles.

Customer Services Field Operations
FCA US LLC