

entity_id,state,last_changed

sensor.heliotherm_heatpump_cop,0.0,2025-11-26T20:00:00.000Z
sensor.heliotherm_heatpump_cop,0.1,2025-11-26T20:33:45.323Z
sensor.heliotherm_heatpump_cop,0.9,2025-11-26T20:34:00.323Z
sensor.heliotherm_heatpump_cop,1.9,2025-11-26T20:34:15.324Z
sensor.heliotherm_heatpump_cop,2.6,2025-11-26T20:34:30.325Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-26T20:34:45.355Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-26T20:35:00.326Z
sensor.heliotherm_heatpump_cop,2.8,2025-11-26T20:35:30.329Z
sensor.heliotherm_heatpump_cop,2.7,2025-11-26T20:35:45.331Z
sensor.heliotherm_heatpump_cop,2.6,2025-11-26T20:36:00.331Z
sensor.heliotherm_heatpump_cop,2.2,2025-11-26T20:37:15.332Z
sensor.heliotherm_heatpump_cop,2.0,2025-11-26T20:37:30.332Z
sensor.heliotherm_heatpump_cop,2.3,2025-11-26T20:37:45.335Z
sensor.heliotherm_heatpump_cop,2.6,2025-11-26T20:38:15.338Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-26T20:38:30.339Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-26T20:38:45.350Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-26T20:39:15.340Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-26T20:39:30.341Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-26T20:39:45.343Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-26T20:40:15.344Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-26T20:40:30.347Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-26T20:41:45.350Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-26T20:42:00.353Z
sensor.heliotherm_heatpump_cop,4.2,2025-11-26T20:42:15.353Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-26T20:42:30.356Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-26T20:42:45.355Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-26T20:43:30.361Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-26T20:43:45.362Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-26T20:44:15.365Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-26T20:44:30.366Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-26T20:44:45.366Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-26T20:45:15.369Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-26T20:47:45.378Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-26T20:48:00.378Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-26T20:48:45.382Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-26T20:49:15.383Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-26T20:49:30.384Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-26T20:49:45.383Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-26T20:51:00.390Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-26T20:51:30.400Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-26T20:51:45.400Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-26T20:52:00.399Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-26T20:52:15.402Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-26T20:52:30.405Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-26T20:52:45.406Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-26T20:53:30.410Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-26T20:53:45.409Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-26T20:54:00.410Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-26T20:54:15.410Z

sensor.heliotherm_heatpump_cop,3.0,2025-11-26T20:54:30.412Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-26T20:54:45.415Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-26T20:55:45.414Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-26T20:56:00.415Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-26T20:56:15.415Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-26T20:56:30.417Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-26T20:56:45.417Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-26T20:57:00.418Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-26T20:59:45.429Z
sensor.heliotherm_heatpump_cop,2.8,2025-11-26T21:00:15.433Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-26T21:00:45.452Z
sensor.heliotherm_heatpump_cop,2.8,2025-11-26T21:01:30.453Z
sensor.heliotherm_heatpump_cop,2.7,2025-11-26T21:01:45.447Z
sensor.heliotherm_heatpump_cop,2.8,2025-11-26T21:02:00.462Z
sensor.heliotherm_heatpump_cop,2.7,2025-11-26T21:03:30.453Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-26T21:04:00.451Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-26T21:06:15.454Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-26T21:07:45.461Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-26T21:08:15.463Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-26T21:08:30.462Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-26T21:08:45.504Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-26T21:09:00.466Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-26T21:09:15.467Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-26T21:09:30.466Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-26T21:10:45.511Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-26T21:11:00.474Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-26T21:11:15.475Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-26T21:11:30.484Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-26T21:11:45.475Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-26T21:12:15.480Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-26T21:12:30.478Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-26T21:14:00.484Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-26T21:14:30.484Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-26T21:14:45.545Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-26T21:15:00.486Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-26T21:15:15.486Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-26T21:15:30.489Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-26T21:15:45.486Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-26T21:16:15.495Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-26T21:16:30.494Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-26T21:17:30.500Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-26T21:17:45.500Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-26T21:19:00.505Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-26T21:19:15.505Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-26T21:19:30.507Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-26T21:19:45.509Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-26T21:20:15.511Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-26T21:21:00.513Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-26T21:21:15.514Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-26T21:21:45.515Z

sensor.heliotherm_heatpump_cop,3.1,2025-11-26T21:22:15.518Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-26T21:23:45.526Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-26T21:24:00.526Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-26T21:24:15.525Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-26T21:24:30.527Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-26T21:25:45.532Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-26T21:26:00.532Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-26T21:27:00.536Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-26T21:27:15.537Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-26T21:28:00.537Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-26T21:28:15.541Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-26T21:28:45.542Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-26T21:29:00.542Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-26T21:29:15.544Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-26T21:29:30.545Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-26T21:29:45.546Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-26T21:30:00.547Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-26T21:30:15.549Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-26T21:30:30.550Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-26T21:31:15.552Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-26T21:31:30.554Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-26T21:34:30.563Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-26T21:34:45.564Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-26T21:35:30.568Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-26T21:36:15.571Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-26T21:36:30.572Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-26T21:37:15.574Z
sensor.heliotherm_heatpump_cop,2.8,2025-11-26T21:37:30.574Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-26T21:38:00.577Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-26T21:38:15.579Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-26T21:38:30.581Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-26T21:38:45.580Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-26T21:39:00.581Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-26T21:39:15.583Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-26T21:39:30.584Z
sensor.heliotherm_heatpump_cop,2.8,2025-11-26T21:39:45.584Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-26T21:40:00.586Z
sensor.heliotherm_heatpump_cop,2.8,2025-11-26T21:40:30.589Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-26T21:40:45.591Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-26T21:41:30.594Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-26T21:41:45.594Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-26T21:42:45.599Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-26T21:43:00.600Z
sensor.heliotherm_heatpump_cop,2.8,2025-11-26T21:43:45.602Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-26T21:44:00.605Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-26T21:45:30.609Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-26T21:45:45.610Z
sensor.heliotherm_heatpump_cop,2.8,2025-11-26T21:47:15.614Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-26T21:47:30.615Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-26T21:47:45.617Z

sensor.heliotherm_heatpump_cop,3.0,2025-11-26T21:48:30.620Z
sensor.heliotherm_heatpump_cop,2.8,2025-11-26T21:49:00.621Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-26T21:49:15.623Z
sensor.heliotherm_heatpump_cop,2.8,2025-11-26T21:57:15.654Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-26T21:57:30.654Z
sensor.heliotherm_heatpump_cop,2.8,2025-11-26T21:58:00.657Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-26T21:58:15.657Z
sensor.heliotherm_heatpump_cop,2.8,2025-11-26T21:58:30.660Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-26T21:58:45.659Z
sensor.heliotherm_heatpump_cop,2.8,2025-11-26T21:59:00.661Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-26T21:59:15.661Z
sensor.heliotherm_heatpump_cop,2.8,2025-11-26T21:59:30.663Z
sensor.heliotherm_heatpump_cop,2.7,2025-11-26T21:59:45.665Z
sensor.heliotherm_heatpump_cop,2.8,2025-11-26T22:00:30.666Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-26T22:00:45.670Z
sensor.heliotherm_heatpump_cop,2.8,2025-11-26T22:01:00.668Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-26T22:01:15.671Z
sensor.heliotherm_heatpump_cop,2.7,2025-11-26T22:01:30.671Z
sensor.heliotherm_heatpump_cop,2.8,2025-11-26T22:01:45.673Z
sensor.heliotherm_heatpump_cop,2.7,2025-11-26T22:09:45.708Z
sensor.heliotherm_heatpump_cop,2.8,2025-11-26T22:10:00.705Z
sensor.heliotherm_heatpump_cop,2.7,2025-11-26T22:10:15.708Z
sensor.heliotherm_heatpump_cop,2.8,2025-11-26T22:10:30.708Z
sensor.heliotherm_heatpump_cop,2.7,2025-11-26T22:11:00.713Z
sensor.heliotherm_heatpump_cop,2.8,2025-11-26T22:11:15.711Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-26T22:11:45.714Z
sensor.heliotherm_heatpump_cop,4.1,2025-11-26T22:12:00.716Z
sensor.heliotherm_heatpump_cop,53.3,2025-11-26T22:12:15.712Z
sensor.heliotherm_heatpump_cop,0.0,2025-11-26T22:12:30.714Z
sensor.heliotherm_heatpump_cop,0.9,2025-11-26T22:18:15.738Z
sensor.heliotherm_heatpump_cop,1.9,2025-11-26T22:18:30.738Z
sensor.heliotherm_heatpump_cop,2.3,2025-11-26T22:18:45.742Z
sensor.heliotherm_heatpump_cop,2.6,2025-11-26T22:19:00.740Z
sensor.heliotherm_heatpump_cop,2.7,2025-11-26T22:19:15.739Z
sensor.heliotherm_heatpump_cop,2.6,2025-11-26T22:19:30.743Z
sensor.heliotherm_heatpump_cop,2.7,2025-11-26T22:19:45.744Z
sensor.heliotherm_heatpump_cop,2.6,2025-11-26T22:20:15.746Z
sensor.heliotherm_heatpump_cop,2.5,2025-11-26T22:20:45.749Z
sensor.heliotherm_heatpump_cop,2.4,2025-11-26T22:21:15.750Z
sensor.heliotherm_heatpump_cop,2.3,2025-11-26T22:21:45.751Z
sensor.heliotherm_heatpump_cop,2.2,2025-11-26T22:22:00.755Z
sensor.heliotherm_heatpump_cop,1.6,2025-11-26T22:22:15.756Z
sensor.heliotherm_heatpump_cop,2.0,2025-11-26T22:22:30.757Z
sensor.heliotherm_heatpump_cop,2.4,2025-11-26T22:22:45.759Z
sensor.heliotherm_heatpump_cop,2.6,2025-11-26T22:23:00.760Z
sensor.heliotherm_heatpump_cop,2.7,2025-11-26T22:23:15.761Z
sensor.heliotherm_heatpump_cop,2.8,2025-11-26T22:23:30.764Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-26T22:23:45.765Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-26T22:24:30.768Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-26T22:25:15.772Z

sensor.heliotherm_heatpump_cop,3.2,2025-11-26T22:26:00.776Z
sensor.heliotherm_heatpump_cop,4.2,2025-11-26T22:26:30.778Z
sensor.heliotherm_heatpump_cop,3.9,2025-11-26T22:26:45.780Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-26T22:27:00.781Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-26T22:27:45.782Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-26T22:28:15.786Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-26T22:28:45.787Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-26T22:29:15.791Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-26T22:29:45.790Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-26T22:30:00.791Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-26T22:30:30.792Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-26T22:33:45.805Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-26T22:34:00.808Z
sensor.heliotherm_heatpump_cop,2.8,2025-11-26T22:34:15.809Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-26T22:34:30.811Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-26T22:35:00.812Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-26T22:35:15.812Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-26T22:38:00.819Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-26T22:38:15.822Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-26T22:39:30.829Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-26T22:39:45.830Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-26T22:40:30.831Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-26T22:40:45.835Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-26T22:41:30.839Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-26T22:42:00.838Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-26T22:42:15.838Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-26T22:43:45.845Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-26T22:44:00.845Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-26T22:45:30.855Z
sensor.heliotherm_heatpump_cop,2.8,2025-11-26T22:47:15.858Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-26T22:48:45.860Z
sensor.heliotherm_heatpump_cop,2.8,2025-11-26T22:49:00.864Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-26T22:49:15.863Z
sensor.heliotherm_heatpump_cop,2.8,2025-11-26T22:49:30.866Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-26T22:50:00.873Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-26T22:53:00.893Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-26T22:54:45.898Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-26T22:55:00.909Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-26T22:55:15.905Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-26T22:56:45.906Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-26T22:57:15.927Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-26T22:57:45.932Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-26T22:58:00.934Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-26T22:58:15.939Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-26T22:58:30.940Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-26T22:58:45.923Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-26T22:59:00.947Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-26T22:59:15.950Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-26T22:59:30.963Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-26T23:00:00.963Z

sensor.heliotherm_heatpump_cop,3.1,2025-11-26T23:00:15.963Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-26T23:00:30.980Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-26T23:00:45.959Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-26T23:01:00.967Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-26T23:01:15.983Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-26T23:06:00.984Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-26T23:06:15.985Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-26T23:06:30.978Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-26T23:06:46.018Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-26T23:07:00.997Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-26T23:07:15.977Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-26T23:07:30.968Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-26T23:07:46.001Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-26T23:08:00.982Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-26T23:08:15.984Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-26T23:08:30.976Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-26T23:08:46.035Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-26T23:09:30.970Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-26T23:09:45.999Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-26T23:11:46.004Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-26T23:12:15.979Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-26T23:14:15.987Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-26T23:14:30.989Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-26T23:15:30.993Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-26T23:15:46.001Z
sensor.heliotherm_heatpump_cop,2.8,2025-11-26T23:16:00.997Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-26T23:16:15.997Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-26T23:16:30.998Z
sensor.heliotherm_heatpump_cop,2.8,2025-11-26T23:20:01.011Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-26T23:20:16.012Z
sensor.heliotherm_heatpump_cop,2.8,2025-11-26T23:20:31.014Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-26T23:20:46.125Z
sensor.heliotherm_heatpump_cop,2.8,2025-11-26T23:21:01.016Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-26T23:21:16.017Z
sensor.heliotherm_heatpump_cop,2.8,2025-11-26T23:22:16.020Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-26T23:22:31.021Z
sensor.heliotherm_heatpump_cop,2.8,2025-11-26T23:24:01.026Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-26T23:24:16.029Z
sensor.heliotherm_heatpump_cop,2.8,2025-11-26T23:27:16.038Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-26T23:27:31.039Z
sensor.heliotherm_heatpump_cop,2.8,2025-11-26T23:27:46.041Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-26T23:28:01.043Z
sensor.heliotherm_heatpump_cop,2.8,2025-11-26T23:28:31.044Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-26T23:28:46.172Z
sensor.heliotherm_heatpump_cop,2.8,2025-11-26T23:29:01.048Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-26T23:29:16.048Z
sensor.heliotherm_heatpump_cop,2.8,2025-11-26T23:30:16.051Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-26T23:30:31.054Z
sensor.heliotherm_heatpump_cop,2.7,2025-11-26T23:30:46.216Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-26T23:31:01.055Z

sensor.heliotherm_heatpump_cop,2.7,2025-11-26T23:31:16.054Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-26T23:31:31.056Z
sensor.heliotherm_heatpump_cop,2.8,2025-11-26T23:31:46.058Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-26T23:32:16.057Z
sensor.heliotherm_heatpump_cop,2.8,2025-11-26T23:32:31.059Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-26T23:32:46.216Z
sensor.heliotherm_heatpump_cop,2.8,2025-11-26T23:33:01.061Z
sensor.heliotherm_heatpump_cop,2.7,2025-11-26T23:33:16.063Z
sensor.heliotherm_heatpump_cop,2.8,2025-11-26T23:33:31.064Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-26T23:33:46.068Z
sensor.heliotherm_heatpump_cop,2.7,2025-11-26T23:34:01.064Z
sensor.heliotherm_heatpump_cop,2.8,2025-11-26T23:34:16.063Z
sensor.heliotherm_heatpump_cop,2.7,2025-11-26T23:41:01.094Z
sensor.heliotherm_heatpump_cop,2.8,2025-11-26T23:41:16.094Z
sensor.heliotherm_heatpump_cop,2.7,2025-11-26T23:44:16.106Z
sensor.heliotherm_heatpump_cop,2.8,2025-11-26T23:44:31.108Z
sensor.heliotherm_heatpump_cop,2.7,2025-11-26T23:44:46.198Z
sensor.heliotherm_heatpump_cop,2.8,2025-11-26T23:45:01.110Z
sensor.heliotherm_heatpump_cop,2.7,2025-11-26T23:45:16.110Z
sensor.heliotherm_heatpump_cop,2.8,2025-11-26T23:46:16.120Z
sensor.heliotherm_heatpump_cop,2.7,2025-11-26T23:46:31.122Z
sensor.heliotherm_heatpump_cop,2.6,2025-11-26T23:46:46.254Z
sensor.heliotherm_heatpump_cop,2.7,2025-11-26T23:47:01.124Z
sensor.heliotherm_heatpump_cop,2.8,2025-11-26T23:47:16.125Z
sensor.heliotherm_heatpump_cop,2.7,2025-11-26T23:47:31.126Z
sensor.heliotherm_heatpump_cop,2.6,2025-11-26T23:49:16.136Z
sensor.heliotherm_heatpump_cop,2.7,2025-11-26T23:49:31.133Z
sensor.heliotherm_heatpump_cop,2.5,2025-11-26T23:53:16.153Z
sensor.heliotherm_heatpump_cop,2.7,2025-11-26T23:53:31.155Z
sensor.heliotherm_heatpump_cop,2.6,2025-11-26T23:55:31.161Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-26T23:55:46.176Z
sensor.heliotherm_heatpump_cop,4.2,2025-11-26T23:56:01.163Z
sensor.heliotherm_heatpump_cop,50.8,2025-11-26T23:56:16.163Z
sensor.heliotherm_heatpump_cop,0.0,2025-11-26T23:56:31.164Z
sensor.heliotherm_heatpump_cop,0.3,2025-11-27T00:36:01.327Z
sensor.heliotherm_heatpump_cop,1.6,2025-11-27T00:36:16.328Z
sensor.heliotherm_heatpump_cop,2.3,2025-11-27T00:36:31.329Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-27T00:36:46.343Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-27T00:37:01.330Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-27T00:37:31.333Z
sensor.heliotherm_heatpump_cop,2.8,2025-11-27T00:38:16.334Z
sensor.heliotherm_heatpump_cop,2.7,2025-11-27T00:38:46.344Z
sensor.heliotherm_heatpump_cop,2.8,2025-11-27T00:39:01.344Z
sensor.heliotherm_heatpump_cop,2.7,2025-11-27T00:39:16.338Z
sensor.heliotherm_heatpump_cop,2.1,2025-11-27T00:39:31.340Z
sensor.heliotherm_heatpump_cop,2.4,2025-11-27T00:39:46.341Z
sensor.heliotherm_heatpump_cop,2.5,2025-11-27T00:40:01.341Z
sensor.heliotherm_heatpump_cop,2.6,2025-11-27T00:40:16.341Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-27T00:40:31.341Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T00:40:46.343Z

sensor.heliotherm_heatpump_cop,3.3,2025-11-27T00:41:01.345Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T00:41:46.347Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T00:42:16.350Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T00:42:46.352Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T00:43:01.352Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T00:43:16.353Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T00:43:31.353Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T00:43:46.356Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-27T00:44:01.356Z
sensor.heliotherm_heatpump_cop,4.2,2025-11-27T00:44:16.358Z
sensor.heliotherm_heatpump_cop,3.9,2025-11-27T00:44:31.360Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T00:44:46.362Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-27T00:45:01.363Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T00:45:16.363Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T00:45:31.364Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T00:45:46.364Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T00:46:01.364Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T00:46:16.363Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T00:46:31.367Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T00:47:01.370Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T00:47:16.373Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T00:47:46.370Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T00:48:01.375Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T00:48:16.375Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T00:48:46.377Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T00:49:01.379Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T00:49:46.381Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T00:50:16.383Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-27T00:50:46.383Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T00:51:01.386Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T00:52:01.389Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T00:52:46.390Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T00:54:16.397Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T00:54:31.397Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T00:55:46.404Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T00:56:01.404Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T00:56:16.406Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T00:56:31.407Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T00:57:16.409Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T00:57:31.411Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T00:59:01.418Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T00:59:16.419Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T01:00:01.420Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T01:00:31.422Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T01:00:46.424Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T01:01:01.422Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T01:01:16.424Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T01:01:31.424Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T01:01:46.427Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-27T01:03:01.432Z

sensor.heliotherm_heatpump_cop,3.2,2025-11-27T01:03:16.434Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-27T01:03:31.434Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T01:05:01.440Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-27T01:05:16.442Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T01:05:31.443Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-27T01:05:46.443Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-27T01:06:01.443Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T01:06:16.445Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T01:07:46.452Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T01:09:01.458Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T01:09:16.459Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T01:09:31.461Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T01:09:46.461Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T01:10:16.461Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T01:11:46.465Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T01:12:01.469Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T01:12:16.469Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T01:12:31.470Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T01:14:01.476Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T01:14:16.479Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T01:14:31.479Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T01:17:31.488Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T01:17:46.491Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T01:18:31.494Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T01:18:46.495Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T01:19:01.497Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T01:19:16.498Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T01:19:31.501Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T01:19:46.501Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T01:20:16.503Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T01:20:31.507Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T01:20:46.504Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T01:21:01.506Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T01:22:46.514Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T01:23:01.514Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T01:23:16.516Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T01:23:31.518Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T01:23:46.518Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T01:24:01.520Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T01:24:16.520Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T01:24:31.520Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T01:24:46.521Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T01:25:01.523Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T01:25:16.526Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T01:25:31.526Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T01:25:46.526Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T01:26:16.529Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T01:27:46.533Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T01:28:16.535Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T01:29:01.538Z

sensor.heliotherm_heatpump_cop,3.3,2025-11-27T01:29:16.538Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T01:29:31.539Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T01:29:46.541Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T01:30:16.544Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T01:30:31.546Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T01:30:46.546Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T01:31:01.548Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T01:31:16.546Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T01:31:31.548Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T01:31:46.549Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-27T01:32:16.550Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T01:32:31.551Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-27T01:35:16.563Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T01:35:31.565Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-27T01:36:16.568Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T01:36:31.568Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-27T01:38:46.576Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T01:39:01.576Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-27T01:39:46.579Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T01:40:01.580Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-27T01:42:01.587Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T01:42:16.588Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-27T01:42:31.590Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T01:42:46.590Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-27T01:43:31.592Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T01:44:01.594Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-27T01:44:16.596Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T01:44:31.597Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-27T01:44:46.597Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-27T01:47:31.607Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-27T01:48:01.608Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-27T01:49:16.612Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-27T01:49:31.613Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-27T01:50:01.614Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-27T01:50:16.615Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-27T01:50:31.618Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-27T01:50:46.617Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-27T01:51:01.618Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-27T01:51:16.620Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-27T01:51:31.618Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-27T01:51:46.620Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-27T01:52:01.623Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-27T01:52:31.624Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-27T01:53:16.628Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-27T01:57:16.647Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-27T01:57:31.647Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-27T01:58:31.650Z
sensor.heliotherm_heatpump_cop,2.8,2025-11-27T01:59:16.653Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-27T01:59:31.656Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-27T02:00:16.656Z

sensor.heliotherm_heatpump_cop,2.9,2025-11-27T02:00:31.657Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-27T02:02:01.664Z
sensor.heliotherm_heatpump_cop,5.2,2025-11-27T02:02:16.669Z
sensor.heliotherm_heatpump_cop,19.2,2025-11-27T02:02:31.666Z
sensor.heliotherm_heatpump_cop,0.0,2025-11-27T02:02:46.667Z
sensor.heliotherm_heatpump_cop,1.3,2025-11-27T02:40:46.907Z
sensor.heliotherm_heatpump_cop,2.1,2025-11-27T02:41:01.821Z
sensor.heliotherm_heatpump_cop,2.7,2025-11-27T02:41:16.823Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-27T02:41:31.825Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-27T02:41:46.828Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-27T02:42:01.826Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-27T02:42:46.926Z
sensor.heliotherm_heatpump_cop,2.8,2025-11-27T02:43:01.832Z
sensor.heliotherm_heatpump_cop,2.2,2025-11-27T02:44:16.836Z
sensor.heliotherm_heatpump_cop,2.4,2025-11-27T02:44:31.836Z
sensor.heliotherm_heatpump_cop,2.6,2025-11-27T02:44:46.938Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-27T02:45:01.839Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T02:45:16.840Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T02:45:31.839Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T02:45:46.843Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T02:46:16.847Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T02:46:31.845Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T02:46:46.946Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T02:47:01.846Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T02:47:46.850Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T02:48:01.850Z
sensor.heliotherm_heatpump_cop,4.1,2025-11-27T02:48:46.962Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T02:49:16.856Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-27T02:49:31.856Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T02:49:46.857Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T02:50:16.858Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T02:50:31.861Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T02:50:46.974Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T02:51:01.863Z
sensor.heliotherm_heatpump_cop,3.7,2025-11-27T02:51:16.864Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T02:51:31.864Z
sensor.heliotherm_heatpump_cop,3.7,2025-11-27T02:51:46.865Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T02:52:01.864Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T02:52:16.868Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T02:53:16.875Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T02:53:46.875Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T02:54:16.881Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T02:54:47.057Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T02:55:16.884Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T02:55:31.886Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T02:55:46.887Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T02:56:01.889Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T02:56:31.892Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T02:56:47.047Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T02:57:01.891Z

sensor.heliotherm_heatpump_cop,3.5,2025-11-27T02:57:16.892Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T03:00:16.920Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T03:00:31.921Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T03:01:16.925Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T03:02:01.928Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T03:03:01.931Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T03:03:16.932Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T03:04:16.938Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T03:04:31.936Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T03:04:47.037Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T03:05:01.937Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T03:05:31.938Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T03:06:01.942Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T03:06:16.945Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T03:06:31.946Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-27T03:07:46.989Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T03:08:01.951Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T03:08:16.950Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-27T03:09:01.955Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T03:09:16.954Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T03:10:47.028Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-27T03:11:01.963Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T03:11:16.964Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T03:11:31.965Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T03:11:46.997Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T03:12:16.972Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T03:12:31.975Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T03:13:01.978Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T03:13:16.979Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T03:13:31.979Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T03:13:46.996Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T03:14:31.988Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T03:14:47.030Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T03:15:16.991Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T03:15:31.993Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T03:15:46.996Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T03:17:31.999Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T03:17:47.004Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T03:18:47.030Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T03:19:02.006Z
sensor.heliotherm_heatpump_cop,3.7,2025-11-27T03:20:17.011Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T03:20:32.011Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T03:21:32.012Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T03:21:47.014Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T03:22:02.019Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T03:22:17.017Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T03:22:47.020Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T03:23:02.020Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T03:23:47.023Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T03:24:02.025Z

sensor.heliotherm_heatpump_cop,3.5,2025-11-27T03:24:32.025Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T03:25:32.028Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T03:25:47.030Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T03:26:32.030Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T03:26:47.033Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T03:28:02.038Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T03:28:17.040Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T03:28:32.041Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T03:28:47.040Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T03:29:02.044Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T03:29:17.046Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T03:29:32.046Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T03:29:47.048Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T03:30:02.047Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T03:32:02.053Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T03:32:17.054Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T03:33:02.057Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T03:33:17.057Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T03:33:32.059Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T03:33:47.059Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T03:34:17.062Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T03:34:32.064Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T03:34:47.066Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T03:35:02.065Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T03:35:17.068Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T03:35:32.069Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T03:35:47.069Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T03:36:47.074Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T03:37:02.073Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T03:37:17.077Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T03:37:32.077Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T03:39:47.084Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T03:40:02.086Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T03:41:32.097Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T03:41:47.097Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T03:42:47.130Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T03:43:02.111Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T03:43:32.114Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T03:44:02.113Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T03:44:17.118Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T03:45:32.114Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T03:45:47.114Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T03:46:17.116Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T03:46:32.116Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T03:46:47.149Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T03:47:02.118Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T03:48:02.119Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T03:48:17.122Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-27T03:50:47.176Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T03:51:02.137Z

sensor.heliotherm_heatpump_cop,3.1,2025-11-27T03:52:17.136Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T03:52:32.139Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-27T03:52:47.175Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T03:53:02.142Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-27T03:53:17.143Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T03:53:32.145Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-27T03:53:47.145Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T03:54:02.150Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-27T03:54:32.148Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T03:54:47.170Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-27T03:55:02.150Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T03:55:17.151Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-27T03:55:32.149Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-27T03:55:47.154Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-27T03:56:02.155Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T03:56:32.160Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-27T03:56:47.175Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-27T04:01:47.180Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-27T04:05:47.193Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-27T04:06:02.195Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-27T04:06:17.198Z
sensor.heliotherm_heatpump_cop,2.8,2025-11-27T04:08:02.204Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-27T04:08:17.206Z
sensor.heliotherm_heatpump_cop,2.8,2025-11-27T04:08:47.207Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-27T04:09:02.209Z
sensor.heliotherm_heatpump_cop,2.8,2025-11-27T04:09:32.211Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-27T04:09:47.213Z
sensor.heliotherm_heatpump_cop,2.7,2025-11-27T04:10:47.218Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-27T04:11:02.220Z
sensor.heliotherm_heatpump_cop,2.8,2025-11-27T04:11:17.222Z
sensor.heliotherm_heatpump_cop,4.5,2025-11-27T04:12:32.228Z
sensor.heliotherm_heatpump_cop,44.1,2025-11-27T04:12:47.228Z
sensor.heliotherm_heatpump_cop,0.0,2025-11-27T04:13:02.232Z
sensor.heliotherm_heatpump_cop,1.5,2025-11-27T04:19:02.251Z
sensor.heliotherm_heatpump_cop,2.2,2025-11-27T04:19:17.251Z
sensor.heliotherm_heatpump_cop,2.6,2025-11-27T04:19:32.251Z
sensor.heliotherm_heatpump_cop,2.7,2025-11-27T04:19:47.253Z
sensor.heliotherm_heatpump_cop,2.6,2025-11-27T04:20:47.257Z
sensor.heliotherm_heatpump_cop,2.5,2025-11-27T04:21:17.256Z
sensor.heliotherm_heatpump_cop,2.4,2025-11-27T04:22:02.262Z
sensor.heliotherm_heatpump_cop,1.8,2025-11-27T04:22:47.266Z
sensor.heliotherm_heatpump_cop,1.9,2025-11-27T04:23:02.267Z
sensor.heliotherm_heatpump_cop,2.1,2025-11-27T04:23:17.269Z
sensor.heliotherm_heatpump_cop,2.5,2025-11-27T04:23:32.270Z
sensor.heliotherm_heatpump_cop,2.7,2025-11-27T04:23:47.269Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-27T04:24:17.271Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-27T04:24:32.273Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T04:25:02.274Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T04:25:32.279Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T04:25:47.279Z

sensor.heliotherm_heatpump_cop,3.1,2025-11-27T04:26:32.282Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T04:26:47.282Z
sensor.heliotherm_heatpump_cop,3.7,2025-11-27T04:27:02.283Z
sensor.heliotherm_heatpump_cop,4.5,2025-11-27T04:27:17.291Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T04:27:32.286Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-27T04:27:47.289Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-27T04:28:02.289Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T04:28:17.291Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T04:28:32.286Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T04:29:02.291Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T04:29:32.296Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T04:29:47.291Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-27T04:30:17.300Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T04:30:32.299Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-27T04:30:47.298Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-27T04:31:02.298Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-27T04:33:47.307Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-27T04:34:02.308Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-27T04:34:47.313Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-27T04:35:02.315Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-27T04:35:17.314Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-27T04:36:17.323Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T04:36:32.322Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-27T04:39:02.331Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T04:39:17.334Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T04:39:32.335Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-27T04:41:17.345Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-27T04:41:32.344Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T04:41:47.343Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-27T04:43:02.350Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T04:43:17.350Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-27T04:43:32.351Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T04:43:47.354Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-27T04:44:02.353Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-27T04:44:32.356Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-27T04:44:47.358Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-27T04:45:02.358Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-27T04:45:17.361Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-27T04:47:02.367Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-27T04:47:17.368Z
sensor.heliotherm_heatpump_cop,2.8,2025-11-27T04:47:32.368Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-27T04:47:47.369Z
sensor.heliotherm_heatpump_cop,2.8,2025-11-27T04:48:32.373Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-27T04:48:47.374Z
sensor.heliotherm_heatpump_cop,2.8,2025-11-27T04:51:17.385Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-27T04:51:32.386Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-27T04:52:47.390Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-27T04:53:02.392Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-27T04:53:32.395Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-27T04:53:47.396Z

sensor.heliotherm_heatpump_cop,3.1,2025-11-27T04:54:02.397Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-27T04:54:17.400Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-27T04:54:32.399Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T04:55:47.402Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-27T04:58:02.410Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T04:58:17.415Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T04:58:32.413Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T05:00:32.422Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T05:00:47.422Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T05:01:02.423Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T05:01:17.422Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T05:01:32.423Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T05:02:02.427Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T05:02:17.427Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T05:07:02.444Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-27T05:09:47.455Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T05:10:02.456Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-27T05:13:17.468Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-27T05:13:32.468Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T05:13:47.470Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-27T05:14:02.471Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T05:14:17.472Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-27T05:14:32.474Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T05:15:32.476Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-27T05:16:17.478Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T05:16:32.480Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-27T05:16:47.482Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-27T05:18:32.487Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-27T05:18:47.489Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-27T05:20:02.495Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-27T05:20:17.496Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T05:23:02.507Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-27T05:23:17.507Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T05:23:32.509Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-27T05:24:02.513Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-27T05:25:02.514Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-27T05:25:32.515Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-27T05:32:47.542Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-27T05:33:02.543Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-27T05:33:17.546Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-27T05:33:47.549Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-27T05:34:02.550Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-27T05:34:17.552Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-27T05:34:32.554Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-27T05:34:47.549Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-27T05:35:02.552Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-27T05:35:32.558Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-27T05:35:47.560Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-27T05:36:02.560Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-27T05:36:17.562Z

sensor.heliotherm_heatpump_cop,3.1,2025-11-27T05:37:47.568Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-27T05:38:02.574Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-27T05:39:17.591Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-27T05:39:32.591Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-27T05:44:17.637Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-27T05:44:32.625Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-27T05:44:47.615Z
sensor.heliotherm_heatpump_cop,2.8,2025-11-27T05:45:02.646Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-27T05:45:17.643Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-27T05:45:32.644Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-27T05:46:02.631Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-27T05:46:47.634Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-27T05:47:02.643Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-27T05:47:17.646Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-27T05:47:32.645Z
sensor.heliotherm_heatpump_cop,2.8,2025-11-27T05:49:02.647Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-27T05:49:17.646Z
sensor.heliotherm_heatpump_cop,2.8,2025-11-27T05:54:17.632Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-27T05:54:32.641Z
sensor.heliotherm_heatpump_cop,2.8,2025-11-27T05:56:17.633Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-27T05:56:32.640Z
sensor.heliotherm_heatpump_cop,3.7,2025-11-27T05:58:17.639Z
sensor.heliotherm_heatpump_cop,89.5,2025-11-27T05:58:32.638Z
sensor.heliotherm_heatpump_cop,0.0,2025-11-27T05:58:47.714Z
sensor.heliotherm_heatpump_cop,0.6,2025-11-27T06:40:17.808Z
sensor.heliotherm_heatpump_cop,1.8,2025-11-27T06:40:32.809Z
sensor.heliotherm_heatpump_cop,2.4,2025-11-27T06:40:47.859Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-27T06:41:02.811Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-27T06:41:17.812Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-27T06:41:32.811Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-27T06:42:02.813Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-27T06:42:17.815Z
sensor.heliotherm_heatpump_cop,2.8,2025-11-27T06:42:32.815Z
sensor.heliotherm_heatpump_cop,2.1,2025-11-27T06:43:32.819Z
sensor.heliotherm_heatpump_cop,2.2,2025-11-27T06:43:47.820Z
sensor.heliotherm_heatpump_cop,2.3,2025-11-27T06:44:02.822Z
sensor.heliotherm_heatpump_cop,2.4,2025-11-27T06:44:17.821Z
sensor.heliotherm_heatpump_cop,2.7,2025-11-27T06:44:32.823Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-27T06:44:47.858Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T06:45:02.824Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T06:45:17.826Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T06:45:47.827Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T06:46:32.832Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T06:47:47.835Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T06:48:02.838Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T06:48:17.842Z
sensor.heliotherm_heatpump_cop,4.4,2025-11-27T06:48:32.842Z
sensor.heliotherm_heatpump_cop,3.8,2025-11-27T06:48:47.855Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-27T06:49:02.842Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T06:49:32.848Z

sensor.heliotherm_heatpump_cop,3.3,2025-11-27T06:49:47.848Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T06:50:02.848Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T06:50:17.851Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T06:50:32.851Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T06:50:47.855Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T06:51:02.853Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T06:51:17.854Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T06:52:32.858Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T06:52:47.860Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T06:53:02.861Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T06:53:32.861Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T06:53:47.868Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T06:54:02.864Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T06:54:17.866Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T06:54:32.865Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T06:55:02.867Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T06:55:17.869Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T06:55:32.871Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T06:56:17.872Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T06:56:47.878Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T06:57:17.875Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T06:57:32.877Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T06:57:47.879Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T06:58:02.879Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T06:58:32.883Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T06:58:47.887Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T06:59:02.886Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T06:59:17.887Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T06:59:32.888Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T06:59:47.891Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T07:00:17.888Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T07:00:32.891Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T07:00:47.892Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T07:01:02.894Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T07:01:17.895Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T07:02:17.897Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T07:02:32.898Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T07:02:47.900Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T07:03:02.906Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T07:03:17.902Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T07:03:47.903Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T07:04:17.905Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T07:04:32.905Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T07:04:47.905Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T07:05:02.906Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-27T07:05:32.909Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T07:05:47.912Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T07:06:02.909Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-27T07:06:17.911Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T07:06:32.911Z

sensor.heliotherm_heatpump_cop,3.1,2025-11-27T07:06:47.913Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-27T07:07:17.945Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T07:07:32.925Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-27T07:07:47.927Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T07:08:17.930Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-27T07:08:32.931Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-27T07:08:47.931Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-27T07:09:02.930Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T07:09:47.940Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-27T07:10:02.940Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-27T07:10:17.944Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T07:10:32.940Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-27T07:11:47.941Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T07:12:02.944Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-27T07:12:17.944Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T07:12:32.950Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T07:12:47.980Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T07:13:17.953Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T07:13:32.952Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T07:13:47.955Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T07:14:02.958Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T07:14:17.958Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T07:14:32.958Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T07:14:47.992Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T07:15:02.959Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T07:15:17.961Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T07:15:32.962Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T07:16:17.964Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T07:16:48.019Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T07:17:17.968Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T07:17:32.980Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T07:17:47.971Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T07:18:17.974Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T07:18:32.974Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T07:18:48.017Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T07:19:17.985Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T07:19:32.977Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T07:19:47.980Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T07:20:17.982Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T07:20:32.984Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T07:21:17.988Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T07:21:32.989Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T07:21:47.991Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T07:22:17.991Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T07:22:32.992Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T07:23:17.997Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T07:23:32.996Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T07:23:47.998Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T07:24:17.999Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T07:24:33.001Z

sensor.heliotherm_heatpump_cop,3.6,2025-11-27T07:24:48.017Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T07:25:03.005Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T07:25:18.005Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T07:25:48.006Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T07:26:03.006Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T07:26:48.014Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T07:27:03.011Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T07:28:03.013Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T07:28:48.018Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T07:29:03.017Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T07:29:18.019Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T07:29:33.021Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T07:29:48.019Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T07:30:03.022Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T07:30:18.023Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T07:31:33.026Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T07:32:18.029Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T07:32:33.030Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T07:32:48.031Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T07:33:03.032Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T07:33:18.031Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T07:33:48.033Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T07:34:03.036Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T07:34:18.034Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T07:34:48.036Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T07:35:03.036Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T07:35:18.039Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T07:35:33.041Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T07:35:48.040Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-27T07:37:03.045Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T07:37:18.044Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T07:37:33.044Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-27T07:38:18.052Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T07:38:33.053Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-27T07:38:48.054Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T07:39:03.053Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T07:40:18.061Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T07:40:33.060Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T07:40:48.062Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T07:41:33.064Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T07:41:48.067Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T07:42:18.068Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T07:42:33.068Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T07:43:03.072Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T07:43:18.071Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T07:43:33.073Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T07:43:48.072Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T07:44:18.077Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T07:44:48.077Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T07:45:03.080Z

sensor.heliotherm_heatpump_cop,3.4,2025-11-27T07:45:18.081Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T07:45:33.080Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T07:45:48.082Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T07:46:03.081Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T07:46:18.083Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T07:46:33.084Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T07:47:03.085Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T07:47:18.090Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T07:47:33.088Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T07:47:48.091Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T07:48:03.088Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T07:48:33.093Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T07:49:03.095Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T07:49:18.098Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T07:49:33.097Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T07:49:48.098Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T07:52:03.108Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T07:52:33.109Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T07:53:33.115Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T07:54:18.119Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T07:55:03.121Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T07:55:18.122Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T07:56:18.126Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T07:56:33.125Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T07:56:48.124Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T07:57:18.126Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T07:58:33.134Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T07:59:03.131Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T08:00:03.137Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T08:00:18.137Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T08:00:33.138Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T08:00:48.141Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T08:01:03.141Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T08:01:18.142Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T08:01:33.146Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T08:01:48.146Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T08:02:18.149Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T08:02:33.151Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T08:03:03.152Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T08:03:18.171Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T08:03:33.171Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T08:03:48.174Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T08:04:33.174Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T08:05:18.181Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T08:05:33.181Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T08:05:48.181Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T08:06:18.183Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T08:06:33.184Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T08:06:48.186Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T08:07:03.186Z

sensor.heliotherm_heatpump_cop,3.4,2025-11-27T08:07:33.188Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T08:08:18.191Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T08:08:33.191Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T08:08:48.193Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T08:09:03.194Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T08:09:18.193Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T08:10:48.199Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T08:11:18.202Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T08:11:33.204Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T08:11:48.204Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T08:12:03.206Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T08:12:33.207Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T08:13:03.209Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T08:13:18.211Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T08:13:33.212Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T08:13:48.213Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T08:14:48.217Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T08:15:03.216Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T08:15:18.218Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T08:15:33.218Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T08:15:48.220Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T08:16:18.219Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T08:16:33.222Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T08:17:48.228Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T08:18:03.227Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T08:18:18.230Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T08:18:33.230Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T08:19:33.236Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T08:20:18.237Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T08:20:33.237Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T08:20:48.241Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T08:21:18.242Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T08:21:33.244Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T08:21:48.246Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T08:22:18.247Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T08:22:33.247Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T08:23:03.249Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T08:23:18.249Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T08:23:33.252Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T08:23:48.253Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T08:24:03.254Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T08:24:18.255Z
sensor.heliotherm_heatpump_cop,5.8,2025-11-27T08:24:33.255Z
sensor.heliotherm_heatpump_cop,42.2,2025-11-27T08:24:48.259Z
sensor.heliotherm_heatpump_cop,0.0,2025-11-27T08:25:03.258Z
sensor.heliotherm_heatpump_cop,1.7,2025-11-27T08:30:18.278Z
sensor.heliotherm_heatpump_cop,2.4,2025-11-27T08:30:33.279Z
sensor.heliotherm_heatpump_cop,2.8,2025-11-27T08:30:48.286Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-27T08:31:03.281Z
sensor.heliotherm_heatpump_cop,2.8,2025-11-27T08:32:18.283Z

sensor.heliotherm_heatpump_cop,2.7,2025-11-27T08:32:48.288Z
sensor.heliotherm_heatpump_cop,2.6,2025-11-27T08:33:33.293Z
sensor.heliotherm_heatpump_cop,2.5,2025-11-27T08:34:03.294Z
sensor.heliotherm_heatpump_cop,2.0,2025-11-27T08:34:18.293Z
sensor.heliotherm_heatpump_cop,2.4,2025-11-27T08:34:33.297Z
sensor.heliotherm_heatpump_cop,2.6,2025-11-27T08:34:48.297Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-27T08:35:03.297Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-27T08:35:18.300Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-27T08:35:33.300Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T08:35:48.301Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T08:36:03.298Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T08:36:18.302Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T08:36:33.304Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T08:37:03.305Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T08:37:18.304Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T08:37:33.305Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T08:37:48.306Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T08:38:18.311Z
sensor.heliotherm_heatpump_cop,4.6,2025-11-27T08:38:33.310Z
sensor.heliotherm_heatpump_cop,3.8,2025-11-27T08:38:48.310Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T08:39:03.312Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T08:39:18.313Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T08:39:33.313Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T08:40:03.314Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T08:40:18.316Z
sensor.heliotherm_heatpump_cop,3.7,2025-11-27T08:40:33.319Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T08:40:48.320Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T08:41:03.322Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T08:41:18.322Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T08:41:33.322Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T08:42:33.327Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T08:42:48.327Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T08:43:03.328Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T08:43:18.330Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T08:43:33.331Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T08:43:48.332Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T08:44:18.335Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T08:44:48.338Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T08:45:03.339Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T08:45:18.340Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T08:45:33.340Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T08:45:48.343Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T08:47:33.349Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T08:47:48.351Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T08:48:03.348Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T08:48:18.351Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T08:48:33.354Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T08:49:03.357Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T08:49:18.357Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T08:49:33.360Z

sensor.heliotherm_heatpump_cop,3.3,2025-11-27T08:49:48.359Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T08:50:03.358Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T08:50:18.359Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T08:50:48.361Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T08:51:33.363Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T08:51:48.365Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T08:52:18.367Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T08:53:03.369Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T08:53:18.369Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T08:53:33.372Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T08:53:48.374Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T08:54:33.376Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T08:54:48.376Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T08:55:33.379Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T08:55:48.381Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T08:56:03.381Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T08:57:03.395Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T08:58:18.423Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-27T08:58:48.419Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T08:59:03.408Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-27T08:59:18.414Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-27T08:59:33.430Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-27T09:00:03.429Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-27T09:00:18.441Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-27T09:01:03.415Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-27T09:01:18.440Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-27T09:01:33.412Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-27T09:01:48.445Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-27T09:02:33.450Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-27T09:02:48.449Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-27T09:03:03.438Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-27T09:03:33.454Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-27T09:03:48.455Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T09:04:18.475Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-27T09:04:33.461Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T09:04:48.461Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-27T09:05:03.459Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T09:05:18.482Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T09:05:33.482Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T09:05:48.485Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T09:06:03.470Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T09:07:03.467Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T09:07:18.480Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T09:07:48.480Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T09:08:03.482Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T09:08:18.472Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T09:08:33.482Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T09:09:18.478Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T09:09:33.480Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T09:09:48.478Z

sensor.heliotherm_heatpump_cop,3.5,2025-11-27T09:10:33.476Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T09:10:48.477Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T09:11:03.495Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T09:11:48.478Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T09:12:18.468Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T09:12:33.475Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T09:12:48.483Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T09:13:03.509Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T09:13:48.481Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T09:14:03.507Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T09:14:48.481Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T09:15:03.524Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T09:15:18.473Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T09:15:48.478Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T09:16:03.501Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T09:16:33.467Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T09:16:48.478Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T09:17:03.535Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T09:17:33.474Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T09:17:48.478Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T09:18:03.502Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T09:18:18.476Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T09:18:33.474Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T09:18:48.478Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T09:19:48.478Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T09:20:03.502Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T09:20:18.482Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T09:20:33.478Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T09:20:48.482Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T09:21:18.483Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T09:21:33.486Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T09:21:48.488Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T09:22:03.495Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T09:22:18.490Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T09:23:18.492Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T09:23:48.494Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T09:24:03.498Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T09:24:18.498Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T09:24:33.497Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T09:24:48.500Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T09:25:03.582Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T09:25:18.499Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T09:25:33.500Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T09:25:48.499Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T09:26:03.501Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T09:26:18.501Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T09:26:33.504Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T09:27:03.599Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T09:27:18.506Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T09:28:18.511Z

sensor.heliotherm_heatpump_cop,3.4,2025-11-27T09:28:33.511Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T09:29:18.518Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T09:30:33.525Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T09:31:03.637Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T09:31:18.527Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T09:31:33.531Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T09:32:33.531Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T09:32:48.535Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T09:33:03.650Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T09:33:48.538Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T09:34:03.539Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T09:34:18.538Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T09:34:33.541Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T09:34:48.542Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T09:36:18.547Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T09:36:33.549Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T09:36:48.548Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T09:37:18.550Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T09:37:33.552Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T09:38:03.552Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T09:38:18.554Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T09:38:33.556Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T09:38:48.557Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T09:39:03.710Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T09:39:18.559Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T09:39:33.559Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T09:39:48.561Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T09:40:33.563Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T09:41:18.569Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T09:42:03.573Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T09:42:18.571Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T09:42:33.572Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T09:42:48.572Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T09:43:48.577Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T09:44:03.588Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T09:44:18.578Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T09:45:18.585Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T09:45:48.588Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T09:46:03.614Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T09:46:18.589Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T09:47:18.593Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T09:48:48.599Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T09:51:03.701Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T09:51:18.607Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T09:51:48.610Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T09:52:03.661Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T09:52:33.612Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T09:52:48.612Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T09:53:03.700Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T09:53:18.617Z

sensor.heliotherm_heatpump_cop,3.4,2025-11-27T09:53:33.619Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T09:54:33.622Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T09:54:48.624Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T09:55:03.698Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T09:55:18.626Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T09:56:03.660Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T09:56:48.633Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T09:57:03.698Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T09:57:18.635Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T09:57:33.634Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T09:58:03.661Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T09:58:33.638Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T09:58:48.640Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T09:59:03.698Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T09:59:18.642Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T09:59:33.643Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T10:00:03.653Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T10:00:18.647Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T10:00:33.648Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T10:01:03.695Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T10:01:48.653Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T10:02:03.660Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T10:02:18.658Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T10:02:48.657Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T10:03:33.661Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T10:03:48.662Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T10:04:03.661Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T10:04:33.664Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T10:04:48.669Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T10:05:03.694Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T10:05:18.668Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T10:05:33.669Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T10:07:18.675Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T10:07:48.677Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T10:08:48.681Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T10:09:18.681Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T10:09:33.683Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T10:10:03.689Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T10:10:18.687Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T10:10:33.690Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T10:10:48.691Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T10:11:03.695Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T10:11:18.693Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T10:12:48.698Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T10:13:03.700Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T10:13:18.702Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T10:13:33.702Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T10:13:48.702Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T10:14:03.704Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T10:14:33.705Z

sensor.heliotherm_heatpump_cop,3.3,2025-11-27T10:14:48.705Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T10:15:03.707Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T10:15:18.708Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T10:15:33.710Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T10:16:03.713Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T10:16:18.713Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T10:16:33.714Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T10:16:48.714Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T10:17:03.714Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T10:17:18.714Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T10:17:33.716Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T10:18:03.719Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T10:18:18.720Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T10:18:33.720Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T10:19:03.724Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T10:19:18.724Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T10:19:33.725Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T10:19:48.726Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T10:20:03.729Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T10:20:18.731Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T10:20:48.731Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T10:21:03.734Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T10:21:18.735Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T10:21:33.736Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T10:22:03.736Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T10:25:03.748Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T10:25:18.746Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-27T10:25:33.749Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T10:25:48.749Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T10:26:03.749Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T10:27:33.754Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T10:27:48.757Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T10:29:33.765Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T10:29:48.767Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T10:30:48.780Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T10:31:03.824Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T10:31:18.780Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T10:31:33.779Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-27T10:31:48.779Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T10:32:03.780Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T10:32:18.778Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T10:32:33.778Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-27T10:32:48.780Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T10:33:03.806Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-27T10:33:48.783Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T10:34:03.783Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T10:35:18.788Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T10:35:33.789Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T10:36:33.793Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T10:36:48.792Z

sensor.heliotherm_heatpump_cop,3.2,2025-11-27T10:37:03.832Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T10:37:18.796Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T10:38:33.800Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-27T10:38:48.796Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T10:39:03.854Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-27T10:39:18.801Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T10:40:03.805Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T10:40:18.807Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T10:40:33.807Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-27T10:40:48.809Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T10:41:03.847Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-27T10:41:18.813Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T10:41:33.812Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-27T10:41:48.816Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T10:42:03.817Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T10:43:48.824Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T10:44:03.823Z
sensor.heliotherm_heatpump_cop,4.3,2025-11-27T10:44:48.830Z
sensor.heliotherm_heatpump_cop,0.0,2025-11-27T10:45:03.861Z
sensor.heliotherm_heatpump_cop,1.4,2025-11-27T11:50:04.112Z
sensor.heliotherm_heatpump_cop,2.2,2025-11-27T11:50:19.116Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-27T11:50:34.117Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T11:50:49.119Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T11:51:34.122Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T11:51:49.123Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T11:52:04.125Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-27T11:52:19.125Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-27T11:52:49.128Z
sensor.heliotherm_heatpump_cop,2.8,2025-11-27T11:53:19.128Z
sensor.heliotherm_heatpump_cop,2.4,2025-11-27T11:53:34.131Z
sensor.heliotherm_heatpump_cop,2.5,2025-11-27T11:53:49.131Z
sensor.heliotherm_heatpump_cop,2.6,2025-11-27T11:54:04.133Z
sensor.heliotherm_heatpump_cop,2.8,2025-11-27T11:54:19.133Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-27T11:54:34.135Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-27T11:54:49.137Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T11:55:04.137Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T11:55:19.135Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T11:55:34.136Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T11:55:49.138Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T11:56:04.139Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T11:56:19.140Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T11:56:49.139Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T11:57:04.143Z
sensor.heliotherm_heatpump_cop,3.8,2025-11-27T11:58:04.143Z
sensor.heliotherm_heatpump_cop,4.7,2025-11-27T11:58:19.147Z
sensor.heliotherm_heatpump_cop,4.4,2025-11-27T11:58:34.149Z
sensor.heliotherm_heatpump_cop,3.7,2025-11-27T11:58:49.150Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-27T11:59:04.175Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T11:59:19.152Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T11:59:34.153Z

sensor.heliotherm_heatpump_cop,3.7,2025-11-27T12:00:34.155Z
sensor.heliotherm_heatpump_cop,3.8,2025-11-27T12:00:49.159Z
sensor.heliotherm_heatpump_cop,3.7,2025-11-27T12:01:04.159Z
sensor.heliotherm_heatpump_cop,3.8,2025-11-27T12:01:19.161Z
sensor.heliotherm_heatpump_cop,3.7,2025-11-27T12:01:34.162Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T12:01:49.162Z
sensor.heliotherm_heatpump_cop,3.8,2025-11-27T12:02:04.164Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T12:02:19.165Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T12:02:49.168Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T12:03:04.167Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T12:03:19.168Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T12:03:34.172Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T12:03:49.174Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T12:04:04.171Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T12:04:19.173Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T12:04:49.176Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T12:05:34.178Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T12:05:49.179Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T12:06:34.181Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T12:06:49.184Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T12:07:04.183Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T12:07:19.185Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T12:08:34.195Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T12:08:49.191Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T12:09:19.194Z
sensor.heliotherm_heatpump_cop,3.7,2025-11-27T12:09:34.195Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T12:09:49.196Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T12:10:34.199Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T12:10:49.198Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T12:11:19.201Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T12:11:34.203Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T12:12:34.207Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T12:14:19.214Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T12:14:34.218Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T12:14:49.219Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T12:15:04.222Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T12:15:19.221Z
sensor.heliotherm_heatpump_cop,5.1,2025-11-27T12:15:49.220Z
sensor.heliotherm_heatpump_cop,98.2,2025-11-27T12:16:04.237Z
sensor.heliotherm_heatpump_cop,0.0,2025-11-27T12:16:19.236Z
sensor.heliotherm_heatpump_cop,0.8,2025-11-27T12:21:19.267Z
sensor.heliotherm_heatpump_cop,2.2,2025-11-27T12:21:34.281Z
sensor.heliotherm_heatpump_cop,2.8,2025-11-27T12:21:49.284Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-27T12:22:04.285Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-27T12:23:19.286Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-27T12:23:34.296Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-27T12:23:49.313Z
sensor.heliotherm_heatpump_cop,2.8,2025-11-27T12:24:04.301Z
sensor.heliotherm_heatpump_cop,2.5,2025-11-27T12:25:19.304Z
sensor.heliotherm_heatpump_cop,2.3,2025-11-27T12:25:34.317Z

sensor.heliotherm_heatpump_cop,2.5,2025-11-27T12:25:49.318Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-27T12:26:04.317Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-27T12:26:19.319Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T12:26:34.309Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T12:26:49.317Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T12:27:34.317Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T12:28:34.311Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T12:28:49.315Z
sensor.heliotherm_heatpump_cop,4.7,2025-11-27T12:29:34.315Z
sensor.heliotherm_heatpump_cop,5.0,2025-11-27T12:29:49.316Z
sensor.heliotherm_heatpump_cop,3.7,2025-11-27T12:30:04.316Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T12:30:19.340Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T12:30:34.308Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T12:30:49.316Z
sensor.heliotherm_heatpump_cop,3.8,2025-11-27T12:31:04.319Z
sensor.heliotherm_heatpump_cop,3.9,2025-11-27T12:31:19.352Z
sensor.heliotherm_heatpump_cop,3.8,2025-11-27T12:31:49.313Z
sensor.heliotherm_heatpump_cop,4.0,2025-11-27T12:32:04.318Z
sensor.heliotherm_heatpump_cop,3.9,2025-11-27T12:32:19.344Z
sensor.heliotherm_heatpump_cop,3.7,2025-11-27T12:32:49.311Z
sensor.heliotherm_heatpump_cop,3.8,2025-11-27T12:33:04.318Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T12:33:19.362Z
sensor.heliotherm_heatpump_cop,3.7,2025-11-27T12:33:34.316Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T12:33:49.311Z
sensor.heliotherm_heatpump_cop,3.7,2025-11-27T12:34:04.317Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T12:34:34.321Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T12:35:19.404Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T12:35:49.326Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T12:36:04.326Z
sensor.heliotherm_heatpump_cop,3.7,2025-11-27T12:36:19.351Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T12:37:04.332Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T12:37:34.333Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T12:37:49.332Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T12:38:04.335Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T12:38:19.336Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T12:38:34.337Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T12:38:49.338Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T12:39:04.339Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T12:39:19.443Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T12:40:49.345Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T12:41:19.444Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T12:41:34.348Z
sensor.heliotherm_heatpump_cop,3.7,2025-11-27T12:41:49.352Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T12:42:04.358Z
sensor.heliotherm_heatpump_cop,3.7,2025-11-27T12:42:19.353Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T12:42:34.354Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T12:43:04.356Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T12:43:19.495Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T12:43:34.358Z
sensor.heliotherm_heatpump_cop,3.7,2025-11-27T12:43:49.359Z

sensor.heliotherm_heatpump_cop,3.6,2025-11-27T12:44:04.360Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T12:44:19.361Z
sensor.heliotherm_heatpump_cop,3.8,2025-11-27T12:44:34.361Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T12:44:49.362Z
sensor.heliotherm_heatpump_cop,3.7,2025-11-27T12:45:04.362Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T12:45:19.487Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T12:45:34.364Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T12:45:49.367Z
sensor.heliotherm_heatpump_cop,3.7,2025-11-27T12:46:04.367Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T12:46:19.369Z
sensor.heliotherm_heatpump_cop,3.7,2025-11-27T12:46:34.370Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T12:46:49.374Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T12:47:04.372Z
sensor.heliotherm_heatpump_cop,3.7,2025-11-27T12:47:19.503Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T12:47:34.371Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T12:48:04.376Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T12:48:19.376Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T12:48:34.377Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T12:48:49.376Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T12:49:04.379Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T12:49:19.546Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T12:49:34.380Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T12:49:49.381Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T12:50:04.383Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T12:50:19.384Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T12:51:04.388Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T12:51:19.541Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T12:51:49.389Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T12:52:04.391Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T12:52:19.392Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T12:52:49.397Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T12:53:34.398Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T12:54:34.402Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T12:54:49.401Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T12:55:04.404Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T12:55:19.549Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T12:56:04.407Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T12:56:19.412Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T12:56:34.412Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T12:57:04.414Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T12:57:19.548Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T12:57:34.416Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T12:57:49.416Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T12:58:04.417Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T12:58:19.428Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T12:59:04.420Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T12:59:19.541Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T12:59:34.425Z
sensor.heliotherm_heatpump_cop,3.7,2025-11-27T13:00:04.427Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T13:00:19.448Z

sensor.heliotherm_heatpump_cop,3.7,2025-11-27T13:00:49.430Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T13:01:04.430Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T13:01:49.432Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T13:02:04.434Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T13:02:19.466Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T13:02:49.438Z
sensor.heliotherm_heatpump_cop,3.7,2025-11-27T13:03:04.438Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T13:03:34.442Z
sensor.heliotherm_heatpump_cop,3.7,2025-11-27T13:03:49.441Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T13:04:04.443Z
sensor.heliotherm_heatpump_cop,3.8,2025-11-27T13:04:19.483Z
sensor.heliotherm_heatpump_cop,3.7,2025-11-27T13:04:34.443Z
sensor.heliotherm_heatpump_cop,3.8,2025-11-27T13:04:49.443Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T13:05:04.444Z
sensor.heliotherm_heatpump_cop,3.8,2025-11-27T13:05:19.544Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T13:05:34.446Z
sensor.heliotherm_heatpump_cop,3.8,2025-11-27T13:05:49.447Z
sensor.heliotherm_heatpump_cop,3.7,2025-11-27T13:07:04.453Z
sensor.heliotherm_heatpump_cop,3.9,2025-11-27T13:07:34.453Z
sensor.heliotherm_heatpump_cop,3.8,2025-11-27T13:07:49.454Z
sensor.heliotherm_heatpump_cop,3.7,2025-11-27T13:08:19.498Z
sensor.heliotherm_heatpump_cop,3.8,2025-11-27T13:08:49.457Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T13:09:04.456Z
sensor.heliotherm_heatpump_cop,3.8,2025-11-27T13:09:19.532Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T13:09:34.458Z
sensor.heliotherm_heatpump_cop,3.7,2025-11-27T13:09:49.459Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T13:10:19.498Z
sensor.heliotherm_heatpump_cop,3.7,2025-11-27T13:10:49.463Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T13:11:04.465Z
sensor.heliotherm_heatpump_cop,3.8,2025-11-27T13:11:34.467Z
sensor.heliotherm_heatpump_cop,3.7,2025-11-27T13:11:49.466Z
sensor.heliotherm_heatpump_cop,3.8,2025-11-27T13:12:04.468Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T13:12:19.500Z
sensor.heliotherm_heatpump_cop,3.7,2025-11-27T13:12:34.470Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T13:12:49.470Z
sensor.heliotherm_heatpump_cop,3.7,2025-11-27T13:13:04.472Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T13:13:19.529Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T13:14:04.475Z
sensor.heliotherm_heatpump_cop,3.7,2025-11-27T13:14:19.499Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T13:14:34.477Z
sensor.heliotherm_heatpump_cop,3.7,2025-11-27T13:14:49.477Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T13:15:04.479Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T13:15:49.481Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T13:16:04.481Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T13:16:19.496Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T13:16:34.482Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T13:17:04.483Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T13:17:34.485Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T13:18:04.486Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T13:18:19.496Z

sensor.heliotherm_heatpump_cop,3.4,2025-11-27T13:19:19.534Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T13:19:34.493Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T13:19:49.492Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T13:20:19.494Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T13:20:34.496Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T13:20:49.496Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T13:21:19.528Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T13:21:34.500Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T13:21:49.500Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T13:22:19.502Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T13:22:34.501Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T13:24:34.508Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T13:24:49.510Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T13:25:19.525Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T13:25:49.515Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T13:26:04.517Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T13:26:34.514Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T13:26:49.518Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T13:27:04.518Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T13:27:19.523Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T13:27:34.524Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T13:27:49.523Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T13:28:04.525Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T13:28:19.526Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T13:28:34.527Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T13:29:04.527Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T13:29:19.527Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T13:29:34.529Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T13:29:49.530Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T13:31:04.536Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T13:31:19.537Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T13:31:34.536Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T13:31:49.539Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T13:32:04.537Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T13:32:19.540Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T13:32:49.544Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T13:33:04.544Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T13:33:19.546Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T13:33:49.548Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T13:34:19.550Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T13:34:49.552Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T13:35:04.553Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T13:35:19.554Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T13:35:34.554Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T13:35:49.556Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T13:36:04.556Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T13:36:19.555Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T13:36:34.557Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T13:36:49.559Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T13:37:04.565Z

sensor.heliotherm_heatpump_cop,3.3,2025-11-27T13:37:19.564Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T13:37:34.564Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T13:37:49.566Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T13:38:04.566Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T13:38:19.567Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T13:38:49.570Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T13:39:34.573Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T13:39:49.573Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T13:40:34.580Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T13:40:49.580Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T13:42:04.584Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T13:42:19.586Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T13:42:49.586Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T13:43:04.588Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T13:43:19.590Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T13:43:49.592Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T13:44:19.593Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T13:44:34.594Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T13:44:49.596Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T13:45:04.597Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T13:45:19.602Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T13:45:34.598Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T13:45:49.600Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T13:46:04.600Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T13:46:19.600Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T13:46:34.602Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T13:46:49.604Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T13:47:49.623Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T13:48:34.615Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T13:48:49.625Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T13:49:04.614Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T13:49:19.662Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T13:49:34.616Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T13:49:49.623Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T13:50:04.616Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T13:50:19.621Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T13:50:49.621Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T13:51:04.619Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T13:51:19.663Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T13:51:34.620Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T13:51:49.624Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T13:52:04.624Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T13:52:19.625Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T13:52:34.624Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T13:52:49.627Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T13:53:04.628Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T13:53:19.684Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T13:54:04.634Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T13:54:19.635Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T13:54:34.636Z

sensor.heliotherm_heatpump_cop,3.3,2025-11-27T13:55:34.639Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T13:55:49.642Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T13:56:04.639Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T13:56:19.643Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T13:56:34.640Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T13:57:04.643Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T13:57:19.686Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T13:57:34.647Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T13:58:34.657Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T13:59:04.653Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T13:59:34.654Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T14:00:19.658Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T14:01:04.663Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T14:01:19.671Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T14:01:49.667Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T14:02:04.667Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T14:02:49.669Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T14:03:04.672Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T14:03:19.674Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T14:03:34.674Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T14:03:49.674Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T14:04:19.677Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T14:04:34.678Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T14:04:49.678Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T14:05:04.680Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T14:05:19.681Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T14:05:34.683Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T14:06:04.682Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T14:06:19.687Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T14:06:49.687Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T14:07:04.690Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T14:08:19.695Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T14:08:34.696Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T14:08:49.695Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T14:09:34.699Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T14:10:19.704Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T14:10:49.705Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T14:11:04.706Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T14:11:19.706Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T14:11:34.708Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T14:11:49.709Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T14:12:19.710Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T14:12:34.712Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T14:12:49.714Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T14:13:04.715Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T14:13:19.715Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T14:13:34.716Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T14:13:49.718Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T14:14:34.722Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T14:14:49.723Z

sensor.heliotherm_heatpump_cop,3.3,2025-11-27T14:15:04.723Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T14:15:19.726Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T14:15:34.727Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T14:16:19.732Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T14:16:34.733Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T14:17:04.735Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T14:17:19.737Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T14:18:04.741Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-27T14:18:19.742Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T14:18:34.742Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T14:18:49.743Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T14:19:04.742Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T14:19:49.747Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T14:20:04.752Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T14:20:49.750Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T14:21:04.755Z
sensor.heliotherm_heatpump_cop,0.0,2025-11-27T14:21:19.757Z
sensor.heliotherm_heatpump_cop,1.3,2025-11-27T15:23:50.036Z
sensor.heliotherm_heatpump_cop,2.5,2025-11-27T15:24:05.066Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-27T15:24:20.036Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T15:24:35.037Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T15:24:50.039Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T15:25:50.043Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T15:26:20.046Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-27T15:26:35.046Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-27T15:26:50.048Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-27T15:27:05.048Z
sensor.heliotherm_heatpump_cop,2.4,2025-11-27T15:27:20.051Z
sensor.heliotherm_heatpump_cop,2.8,2025-11-27T15:27:50.054Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-27T15:28:05.055Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-27T15:28:35.058Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T15:28:50.057Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T15:29:05.059Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T15:29:35.063Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T15:30:05.062Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T15:31:05.069Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T15:31:50.071Z
sensor.heliotherm_heatpump_cop,4.8,2025-11-27T15:32:05.074Z
sensor.heliotherm_heatpump_cop,4.6,2025-11-27T15:32:20.077Z
sensor.heliotherm_heatpump_cop,3.8,2025-11-27T15:32:35.082Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T15:32:50.078Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T15:33:05.082Z
sensor.heliotherm_heatpump_cop,3.7,2025-11-27T15:33:20.074Z
sensor.heliotherm_heatpump_cop,3.8,2025-11-27T15:33:35.088Z
sensor.heliotherm_heatpump_cop,3.9,2025-11-27T15:34:05.088Z
sensor.heliotherm_heatpump_cop,4.0,2025-11-27T15:34:35.100Z
sensor.heliotherm_heatpump_cop,4.1,2025-11-27T15:34:50.101Z
sensor.heliotherm_heatpump_cop,4.0,2025-11-27T15:35:05.103Z
sensor.heliotherm_heatpump_cop,3.8,2025-11-27T15:35:20.085Z
sensor.heliotherm_heatpump_cop,3.7,2025-11-27T15:35:35.102Z

sensor.heliotherm_heatpump_cop,3.9,2025-11-27T15:35:50.101Z
sensor.heliotherm_heatpump_cop,3.7,2025-11-27T15:36:35.129Z
sensor.heliotherm_heatpump_cop,3.9,2025-11-27T15:36:50.127Z
sensor.heliotherm_heatpump_cop,3.8,2025-11-27T15:37:05.134Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T15:37:35.134Z
sensor.heliotherm_heatpump_cop,3.8,2025-11-27T15:37:50.134Z
sensor.heliotherm_heatpump_cop,3.7,2025-11-27T15:38:05.135Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T15:38:35.149Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T15:38:50.157Z
sensor.heliotherm_heatpump_cop,3.7,2025-11-27T15:39:05.139Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T15:39:20.129Z
sensor.heliotherm_heatpump_cop,3.7,2025-11-27T15:39:35.158Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T15:39:50.156Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T15:40:05.153Z
sensor.heliotherm_heatpump_cop,3.7,2025-11-27T15:40:20.158Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T15:40:50.154Z
sensor.heliotherm_heatpump_cop,3.7,2025-11-27T15:41:05.156Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T15:41:20.158Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T15:41:35.156Z
sensor.heliotherm_heatpump_cop,3.8,2025-11-27T15:41:50.212Z
sensor.heliotherm_heatpump_cop,3.7,2025-11-27T15:42:05.157Z
sensor.heliotherm_heatpump_cop,3.8,2025-11-27T15:43:05.158Z
sensor.heliotherm_heatpump_cop,3.7,2025-11-27T15:43:20.175Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T15:43:35.156Z
sensor.heliotherm_heatpump_cop,3.7,2025-11-27T15:43:50.154Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T15:44:05.156Z
sensor.heliotherm_heatpump_cop,3.7,2025-11-27T15:44:35.146Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T15:45:05.158Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T15:45:20.186Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T15:45:35.153Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T15:45:50.154Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T15:46:05.153Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T15:46:20.181Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T15:46:35.146Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T15:47:05.157Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T15:48:05.153Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T15:48:35.146Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T15:48:50.148Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T15:49:05.153Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T15:49:35.151Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T15:49:50.154Z
sensor.heliotherm_heatpump_cop,3.9,2025-11-27T15:50:35.155Z
sensor.heliotherm_heatpump_cop,51.1,2025-11-27T15:50:50.156Z
sensor.heliotherm_heatpump_cop,0.0,2025-11-27T15:51:05.158Z
sensor.heliotherm_heatpump_cop,0.7,2025-11-27T15:56:20.179Z
sensor.heliotherm_heatpump_cop,1.6,2025-11-27T15:56:35.180Z
sensor.heliotherm_heatpump_cop,2.4,2025-11-27T15:56:50.180Z
sensor.heliotherm_heatpump_cop,2.8,2025-11-27T15:57:05.181Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-27T15:57:20.279Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T15:58:20.184Z

sensor.heliotherm_heatpump_cop,3.1,2025-11-27T15:58:35.189Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-27T15:59:20.298Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-27T15:59:35.191Z
sensor.heliotherm_heatpump_cop,2.3,2025-11-27T16:00:20.193Z
sensor.heliotherm_heatpump_cop,2.6,2025-11-27T16:00:50.197Z
sensor.heliotherm_heatpump_cop,2.8,2025-11-27T16:01:05.199Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-27T16:01:20.314Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T16:01:35.198Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T16:01:50.201Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T16:02:05.202Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T16:02:20.201Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T16:03:05.203Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T16:03:20.328Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T16:03:35.206Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T16:03:50.206Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T16:04:05.209Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T16:04:20.207Z
sensor.heliotherm_heatpump_cop,3.8,2025-11-27T16:04:35.209Z
sensor.heliotherm_heatpump_cop,5.0,2025-11-27T16:04:50.210Z
sensor.heliotherm_heatpump_cop,4.1,2025-11-27T16:05:05.210Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T16:05:20.326Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T16:05:35.212Z
sensor.heliotherm_heatpump_cop,3.7,2025-11-27T16:05:50.213Z
sensor.heliotherm_heatpump_cop,4.0,2025-11-27T16:06:20.215Z
sensor.heliotherm_heatpump_cop,4.2,2025-11-27T16:07:05.217Z
sensor.heliotherm_heatpump_cop,3.9,2025-11-27T16:07:35.217Z
sensor.heliotherm_heatpump_cop,4.0,2025-11-27T16:07:50.219Z
sensor.heliotherm_heatpump_cop,4.1,2025-11-27T16:08:05.221Z
sensor.heliotherm_heatpump_cop,3.9,2025-11-27T16:08:20.221Z
sensor.heliotherm_heatpump_cop,3.8,2025-11-27T16:09:05.222Z
sensor.heliotherm_heatpump_cop,3.7,2025-11-27T16:11:35.234Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T16:11:50.235Z
sensor.heliotherm_heatpump_cop,3.7,2025-11-27T16:12:05.237Z
sensor.heliotherm_heatpump_cop,3.8,2025-11-27T16:12:20.241Z
sensor.heliotherm_heatpump_cop,3.7,2025-11-27T16:12:35.238Z
sensor.heliotherm_heatpump_cop,3.8,2025-11-27T16:12:50.240Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T16:13:05.239Z
sensor.heliotherm_heatpump_cop,3.8,2025-11-27T16:13:20.387Z
sensor.heliotherm_heatpump_cop,3.7,2025-11-27T16:13:50.240Z
sensor.heliotherm_heatpump_cop,3.8,2025-11-27T16:14:05.244Z
sensor.heliotherm_heatpump_cop,3.7,2025-11-27T16:14:20.246Z
sensor.heliotherm_heatpump_cop,3.9,2025-11-27T16:15:05.249Z
sensor.heliotherm_heatpump_cop,4.0,2025-11-27T16:15:20.390Z
sensor.heliotherm_heatpump_cop,3.7,2025-11-27T16:15:50.247Z
sensor.heliotherm_heatpump_cop,3.8,2025-11-27T16:16:05.251Z
sensor.heliotherm_heatpump_cop,3.9,2025-11-27T16:16:35.252Z
sensor.heliotherm_heatpump_cop,3.8,2025-11-27T16:17:20.379Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T16:19:35.263Z
sensor.heliotherm_heatpump_cop,3.8,2025-11-27T16:19:50.264Z
sensor.heliotherm_heatpump_cop,3.7,2025-11-27T16:20:35.268Z

sensor.heliotherm_heatpump_cop,3.8,2025-11-27T16:20:50.267Z
sensor.heliotherm_heatpump_cop,3.7,2025-11-27T16:21:05.268Z
sensor.heliotherm_heatpump_cop,3.8,2025-11-27T16:21:20.383Z
sensor.heliotherm_heatpump_cop,3.7,2025-11-27T16:21:35.272Z
sensor.heliotherm_heatpump_cop,3.8,2025-11-27T16:21:50.273Z
sensor.heliotherm_heatpump_cop,3.7,2025-11-27T16:22:05.274Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T16:22:35.274Z
sensor.heliotherm_heatpump_cop,3.7,2025-11-27T16:22:50.276Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T16:23:05.276Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T16:23:20.383Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T16:23:50.280Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T16:25:05.284Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T16:25:20.375Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T16:25:35.287Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T16:25:50.286Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T16:26:20.333Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T16:26:35.289Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T16:27:05.290Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T16:27:20.375Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T16:27:35.293Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T16:27:50.295Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T16:28:05.296Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T16:28:35.299Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T16:28:50.298Z
sensor.heliotherm_heatpump_cop,3.7,2025-11-27T16:29:20.373Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T16:29:35.304Z
sensor.heliotherm_heatpump_cop,3.7,2025-11-27T16:29:50.305Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T16:31:05.308Z
sensor.heliotherm_heatpump_cop,3.7,2025-11-27T16:31:20.370Z
sensor.heliotherm_heatpump_cop,3.8,2025-11-27T16:31:35.309Z
sensor.heliotherm_heatpump_cop,3.7,2025-11-27T16:31:50.309Z
sensor.heliotherm_heatpump_cop,3.8,2025-11-27T16:32:05.310Z
sensor.heliotherm_heatpump_cop,3.7,2025-11-27T16:32:20.333Z
sensor.heliotherm_heatpump_cop,3.8,2025-11-27T16:33:20.372Z
sensor.heliotherm_heatpump_cop,3.7,2025-11-27T16:33:35.314Z
sensor.heliotherm_heatpump_cop,3.8,2025-11-27T16:33:50.315Z
sensor.heliotherm_heatpump_cop,3.7,2025-11-27T16:34:05.318Z
sensor.heliotherm_heatpump_cop,3.8,2025-11-27T16:34:20.331Z
sensor.heliotherm_heatpump_cop,3.7,2025-11-27T16:34:35.321Z
sensor.heliotherm_heatpump_cop,3.8,2025-11-27T16:34:50.320Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T16:35:05.322Z
sensor.heliotherm_heatpump_cop,3.8,2025-11-27T16:35:20.362Z
sensor.heliotherm_heatpump_cop,3.9,2025-11-27T16:36:05.325Z
sensor.heliotherm_heatpump_cop,3.8,2025-11-27T16:36:20.330Z
sensor.heliotherm_heatpump_cop,3.7,2025-11-27T16:36:35.328Z
sensor.heliotherm_heatpump_cop,3.8,2025-11-27T16:36:50.328Z
sensor.heliotherm_heatpump_cop,3.9,2025-11-27T16:37:05.328Z
sensor.heliotherm_heatpump_cop,3.7,2025-11-27T16:37:35.330Z
sensor.heliotherm_heatpump_cop,3.9,2025-11-27T16:37:50.332Z
sensor.heliotherm_heatpump_cop,4.0,2025-11-27T16:38:20.334Z

sensor.heliotherm_heatpump_cop,3.6,2025-11-27T16:38:50.335Z
sensor.heliotherm_heatpump_cop,3.8,2025-11-27T16:39:05.336Z
sensor.heliotherm_heatpump_cop,3.7,2025-11-27T16:39:35.338Z
sensor.heliotherm_heatpump_cop,3.9,2025-11-27T16:39:50.338Z
sensor.heliotherm_heatpump_cop,3.8,2025-11-27T16:40:05.338Z
sensor.heliotherm_heatpump_cop,3.9,2025-11-27T16:40:20.340Z
sensor.heliotherm_heatpump_cop,3.8,2025-11-27T16:40:35.342Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T16:40:50.343Z
sensor.heliotherm_heatpump_cop,3.8,2025-11-27T16:41:05.341Z
sensor.heliotherm_heatpump_cop,3.9,2025-11-27T16:41:35.344Z
sensor.heliotherm_heatpump_cop,3.8,2025-11-27T16:41:50.345Z
sensor.heliotherm_heatpump_cop,4.0,2025-11-27T16:42:05.345Z
sensor.heliotherm_heatpump_cop,3.7,2025-11-27T16:42:20.345Z
sensor.heliotherm_heatpump_cop,3.8,2025-11-27T16:42:50.349Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T16:43:05.349Z
sensor.heliotherm_heatpump_cop,3.8,2025-11-27T16:43:20.358Z
sensor.heliotherm_heatpump_cop,4.0,2025-11-27T16:44:20.356Z
sensor.heliotherm_heatpump_cop,3.9,2025-11-27T16:44:35.356Z
sensor.heliotherm_heatpump_cop,3.7,2025-11-27T16:44:50.357Z
sensor.heliotherm_heatpump_cop,3.8,2025-11-27T16:45:05.361Z
sensor.heliotherm_heatpump_cop,3.7,2025-11-27T16:45:20.359Z
sensor.heliotherm_heatpump_cop,3.8,2025-11-27T16:45:35.359Z
sensor.heliotherm_heatpump_cop,3.7,2025-11-27T16:45:50.361Z
sensor.heliotherm_heatpump_cop,3.8,2025-11-27T16:46:05.361Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T16:46:20.364Z
sensor.heliotherm_heatpump_cop,3.7,2025-11-27T16:47:05.366Z
sensor.heliotherm_heatpump_cop,3.8,2025-11-27T16:47:20.368Z
sensor.heliotherm_heatpump_cop,3.7,2025-11-27T16:48:05.369Z
sensor.heliotherm_heatpump_cop,3.8,2025-11-27T16:48:20.370Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T16:48:35.373Z
sensor.heliotherm_heatpump_cop,3.8,2025-11-27T16:48:50.371Z
sensor.heliotherm_heatpump_cop,3.7,2025-11-27T16:49:20.405Z
sensor.heliotherm_heatpump_cop,3.8,2025-11-27T16:49:35.377Z
sensor.heliotherm_heatpump_cop,3.7,2025-11-27T16:49:50.376Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T16:50:05.377Z
sensor.heliotherm_heatpump_cop,3.7,2025-11-27T16:50:20.379Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T16:51:35.382Z
sensor.heliotherm_heatpump_cop,3.7,2025-11-27T16:51:50.383Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T16:52:05.383Z
sensor.heliotherm_heatpump_cop,3.7,2025-11-27T16:52:20.385Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T16:53:20.388Z
sensor.heliotherm_heatpump_cop,3.7,2025-11-27T16:53:35.387Z
sensor.heliotherm_heatpump_cop,3.8,2025-11-27T16:55:35.399Z
sensor.heliotherm_heatpump_cop,3.7,2025-11-27T16:55:50.398Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T16:56:20.397Z
sensor.heliotherm_heatpump_cop,3.7,2025-11-27T16:56:35.402Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T17:00:05.415Z
sensor.heliotherm_heatpump_cop,3.7,2025-11-27T17:00:20.415Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T17:01:05.422Z
sensor.heliotherm_heatpump_cop,3.7,2025-11-27T17:01:20.422Z

sensor.heliotherm_heatpump_cop,3.6,2025-11-27T17:01:35.421Z
sensor.heliotherm_heatpump_cop,3.7,2025-11-27T17:02:35.425Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T17:02:50.427Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T17:04:35.433Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T17:04:50.435Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T17:05:20.440Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T17:05:35.439Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T17:06:35.450Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T17:06:50.451Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T17:07:05.450Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T17:07:20.462Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T17:07:35.451Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T17:08:20.450Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T17:08:50.451Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T17:09:05.451Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T17:09:50.454Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T17:10:05.454Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T17:10:20.456Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T17:11:05.460Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T17:11:20.491Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T17:12:20.464Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T17:12:35.465Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T17:13:05.466Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T17:13:20.519Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T17:13:35.469Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T17:14:50.477Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T17:15:05.477Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T17:15:20.535Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T17:15:35.480Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T17:18:50.489Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T17:19:05.486Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T17:19:20.521Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T17:19:35.492Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T17:19:50.493Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T17:21:05.495Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T17:21:20.520Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T17:26:05.511Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T17:26:35.516Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T17:26:50.516Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T17:27:50.520Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T17:28:05.521Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T17:28:35.524Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T17:28:50.524Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T17:29:35.527Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T17:29:50.528Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T17:30:05.529Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T17:30:20.529Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T17:30:50.532Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T17:31:05.534Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T17:31:20.534Z

sensor.heliotherm_heatpump_cop,3.5,2025-11-27T17:31:35.534Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T17:31:50.535Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T17:32:05.536Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T17:32:20.535Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T17:32:50.539Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T17:33:05.540Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T17:33:20.542Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T17:33:35.542Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T17:37:20.557Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T17:37:35.557Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T17:37:50.557Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T17:38:20.560Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T17:38:50.563Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T17:40:20.570Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T17:40:35.574Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T17:41:20.579Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T17:41:35.580Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T17:42:05.583Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T17:42:35.587Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T17:42:50.583Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T17:43:05.585Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T17:43:20.588Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T17:44:20.593Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T17:44:35.595Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T17:44:50.597Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T17:45:05.598Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T17:45:20.595Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T17:45:35.599Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T17:45:50.604Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T17:46:05.602Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T17:46:20.603Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T17:46:35.604Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T17:46:50.603Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T17:47:05.606Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T17:47:20.606Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T17:47:35.608Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T17:48:20.609Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T17:48:50.612Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T17:49:05.613Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T17:49:20.614Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T17:49:35.616Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T17:49:50.617Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T17:50:05.618Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T17:50:20.618Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T17:50:50.620Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T17:51:05.621Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T17:51:20.622Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T17:51:35.621Z
sensor.heliotherm_heatpump_cop,5.5,2025-11-27T17:52:05.625Z
sensor.heliotherm_heatpump_cop,0.0,2025-11-27T17:52:20.625Z

sensor.heliotherm_heatpump_cop,0.1,2025-11-27T18:53:20.883Z
sensor.heliotherm_heatpump_cop,1.9,2025-11-27T18:53:35.884Z
sensor.heliotherm_heatpump_cop,2.8,2025-11-27T18:53:50.884Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T18:54:05.885Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T18:54:20.889Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T18:54:35.887Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T18:55:05.892Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T18:55:35.896Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T18:56:05.899Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T18:56:20.898Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-27T18:56:50.903Z
sensor.heliotherm_heatpump_cop,2.6,2025-11-27T18:57:05.904Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-27T18:57:35.904Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-27T18:57:50.906Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T18:58:20.909Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T18:58:50.932Z
sensor.heliotherm_heatpump_cop,3.3,2025-11-27T18:59:05.920Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T18:59:20.911Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T19:00:05.927Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T19:00:35.931Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T19:00:50.942Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T19:01:05.945Z
sensor.heliotherm_heatpump_cop,4.3,2025-11-27T19:01:35.946Z
sensor.heliotherm_heatpump_cop,4.9,2025-11-27T19:01:50.948Z
sensor.heliotherm_heatpump_cop,4.2,2025-11-27T19:02:05.944Z
sensor.heliotherm_heatpump_cop,3.8,2025-11-27T19:02:20.950Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T19:02:35.953Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T19:02:50.963Z
sensor.heliotherm_heatpump_cop,3.8,2025-11-27T19:03:05.960Z
sensor.heliotherm_heatpump_cop,4.0,2025-11-27T19:03:20.936Z
sensor.heliotherm_heatpump_cop,4.1,2025-11-27T19:03:35.959Z
sensor.heliotherm_heatpump_cop,4.2,2025-11-27T19:03:50.960Z
sensor.heliotherm_heatpump_cop,3.9,2025-11-27T19:04:05.963Z
sensor.heliotherm_heatpump_cop,4.1,2025-11-27T19:04:20.966Z
sensor.heliotherm_heatpump_cop,3.9,2025-11-27T19:05:05.979Z
sensor.heliotherm_heatpump_cop,3.8,2025-11-27T19:05:20.962Z
sensor.heliotherm_heatpump_cop,4.0,2025-11-27T19:05:35.988Z
sensor.heliotherm_heatpump_cop,4.1,2025-11-27T19:05:50.985Z
sensor.heliotherm_heatpump_cop,3.9,2025-11-27T19:06:20.979Z
sensor.heliotherm_heatpump_cop,3.7,2025-11-27T19:07:05.980Z
sensor.heliotherm_heatpump_cop,3.9,2025-11-27T19:07:20.977Z
sensor.heliotherm_heatpump_cop,3.8,2025-11-27T19:07:35.990Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T19:08:05.986Z
sensor.heliotherm_heatpump_cop,3.8,2025-11-27T19:08:21.008Z
sensor.heliotherm_heatpump_cop,3.7,2025-11-27T19:09:05.979Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T19:09:20.997Z
sensor.heliotherm_heatpump_cop,3.7,2025-11-27T19:09:35.993Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T19:09:50.985Z
sensor.heliotherm_heatpump_cop,3.7,2025-11-27T19:10:05.984Z
sensor.heliotherm_heatpump_cop,3.9,2025-11-27T19:10:35.983Z

sensor.heliotherm_heatpump_cop,3.7,2025-11-27T19:10:50.973Z
sensor.heliotherm_heatpump_cop,3.9,2025-11-27T19:11:21.007Z
sensor.heliotherm_heatpump_cop,3.7,2025-11-27T19:11:50.983Z
sensor.heliotherm_heatpump_cop,3.8,2025-11-27T19:12:05.983Z
sensor.heliotherm_heatpump_cop,3.9,2025-11-27T19:12:21.012Z
sensor.heliotherm_heatpump_cop,3.7,2025-11-27T19:12:35.989Z
sensor.heliotherm_heatpump_cop,3.9,2025-11-27T19:13:05.977Z
sensor.heliotherm_heatpump_cop,3.8,2025-11-27T19:13:21.023Z
sensor.heliotherm_heatpump_cop,3.7,2025-11-27T19:13:35.983Z
sensor.heliotherm_heatpump_cop,3.8,2025-11-27T19:13:50.981Z
sensor.heliotherm_heatpump_cop,3.7,2025-11-27T19:14:05.981Z
sensor.heliotherm_heatpump_cop,3.8,2025-11-27T19:14:35.982Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T19:15:21.041Z
sensor.heliotherm_heatpump_cop,3.8,2025-11-27T19:15:35.980Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T19:16:35.982Z
sensor.heliotherm_heatpump_cop,3.8,2025-11-27T19:16:50.979Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T19:17:05.983Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T19:17:21.056Z
sensor.heliotherm_heatpump_cop,3.7,2025-11-27T19:17:35.986Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T19:18:05.987Z
sensor.heliotherm_heatpump_cop,3.7,2025-11-27T19:18:35.989Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T19:18:50.990Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T19:19:21.077Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T19:19:50.993Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T19:20:05.995Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T19:20:21.003Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T19:21:36.003Z
sensor.heliotherm_heatpump_cop,5.6,2025-11-27T19:21:51.002Z
sensor.heliotherm_heatpump_cop,64.0,2025-11-27T19:22:06.003Z
sensor.heliotherm_heatpump_cop,0.0,2025-11-27T19:22:21.005Z
sensor.heliotherm_heatpump_cop,1.8,2025-11-27T19:27:36.023Z
sensor.heliotherm_heatpump_cop,2.6,2025-11-27T19:27:51.023Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-27T19:28:06.023Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T19:28:21.025Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-27T19:29:36.030Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T19:29:51.033Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-27T19:30:06.033Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-27T19:30:51.036Z
sensor.heliotherm_heatpump_cop,2.9,2025-11-27T19:31:21.156Z
sensor.heliotherm_heatpump_cop,2.4,2025-11-27T19:31:36.038Z
sensor.heliotherm_heatpump_cop,2.6,2025-11-27T19:31:51.038Z
sensor.heliotherm_heatpump_cop,3.0,2025-11-27T19:32:06.039Z
sensor.heliotherm_heatpump_cop,3.1,2025-11-27T19:32:36.042Z
sensor.heliotherm_heatpump_cop,3.2,2025-11-27T19:32:51.044Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T19:33:06.045Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T19:33:21.224Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T19:33:51.047Z
sensor.heliotherm_heatpump_cop,3.7,2025-11-27T19:35:06.050Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T19:35:21.172Z
sensor.heliotherm_heatpump_cop,4.2,2025-11-27T19:35:36.052Z

sensor.heliotherm_heatpump_cop,5.1,2025-11-27T19:35:51.060Z
sensor.heliotherm_heatpump_cop,3.9,2025-11-27T19:36:06.053Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T19:36:21.055Z
sensor.heliotherm_heatpump_cop,3.7,2025-11-27T19:37:06.058Z
sensor.heliotherm_heatpump_cop,4.0,2025-11-27T19:37:21.216Z
sensor.heliotherm_heatpump_cop,4.2,2025-11-27T19:37:51.059Z
sensor.heliotherm_heatpump_cop,4.1,2025-11-27T19:38:06.059Z
sensor.heliotherm_heatpump_cop,3.9,2025-11-27T19:39:21.218Z
sensor.heliotherm_heatpump_cop,3.8,2025-11-27T19:39:51.067Z
sensor.heliotherm_heatpump_cop,3.9,2025-11-27T19:40:06.067Z
sensor.heliotherm_heatpump_cop,3.8,2025-11-27T19:40:21.071Z
sensor.heliotherm_heatpump_cop,3.7,2025-11-27T19:40:36.070Z
sensor.heliotherm_heatpump_cop,3.8,2025-11-27T19:41:06.072Z
sensor.heliotherm_heatpump_cop,3.7,2025-11-27T19:41:21.214Z
sensor.heliotherm_heatpump_cop,3.8,2025-11-27T19:41:36.072Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T19:42:06.074Z
sensor.heliotherm_heatpump_cop,3.8,2025-11-27T19:42:21.077Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T19:42:36.077Z
sensor.heliotherm_heatpump_cop,3.8,2025-11-27T19:43:06.078Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T19:43:21.215Z
sensor.heliotherm_heatpump_cop,3.8,2025-11-27T19:44:21.084Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T19:44:51.084Z
sensor.heliotherm_heatpump_cop,3.9,2025-11-27T19:45:06.096Z
sensor.heliotherm_heatpump_cop,3.7,2025-11-27T19:45:21.232Z
sensor.heliotherm_heatpump_cop,3.9,2025-11-27T19:45:36.096Z
sensor.heliotherm_heatpump_cop,4.0,2025-11-27T19:46:51.101Z
sensor.heliotherm_heatpump_cop,3.8,2025-11-27T19:47:06.101Z
sensor.heliotherm_heatpump_cop,4.0,2025-11-27T19:47:21.266Z
sensor.heliotherm_heatpump_cop,3.9,2025-11-27T19:47:36.103Z
sensor.heliotherm_heatpump_cop,4.0,2025-11-27T19:47:51.104Z
sensor.heliotherm_heatpump_cop,3.9,2025-11-27T19:48:06.105Z
sensor.heliotherm_heatpump_cop,4.0,2025-11-27T19:48:21.143Z
sensor.heliotherm_heatpump_cop,3.8,2025-11-27T19:48:36.108Z
sensor.heliotherm_heatpump_cop,4.1,2025-11-27T19:48:51.110Z
sensor.heliotherm_heatpump_cop,4.0,2025-11-27T19:49:06.110Z
sensor.heliotherm_heatpump_cop,3.8,2025-11-27T19:49:21.225Z
sensor.heliotherm_heatpump_cop,3.9,2025-11-27T19:49:36.111Z
sensor.heliotherm_heatpump_cop,3.7,2025-11-27T19:50:06.113Z
sensor.heliotherm_heatpump_cop,3.9,2025-11-27T19:50:21.152Z
sensor.heliotherm_heatpump_cop,3.7,2025-11-27T19:51:51.119Z
sensor.heliotherm_heatpump_cop,3.8,2025-11-27T19:52:06.120Z
sensor.heliotherm_heatpump_cop,3.7,2025-11-27T19:52:21.175Z
sensor.heliotherm_heatpump_cop,3.8,2025-11-27T19:52:36.122Z
sensor.heliotherm_heatpump_cop,3.7,2025-11-27T19:54:06.127Z
sensor.heliotherm_heatpump_cop,3.8,2025-11-27T19:54:21.178Z
sensor.heliotherm_heatpump_cop,3.7,2025-11-27T19:54:36.127Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T19:55:21.197Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T19:55:51.134Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T19:56:06.135Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T19:56:21.162Z

sensor.heliotherm_heatpump_cop,3.6,2025-11-27T19:56:36.138Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T19:56:51.139Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T19:57:06.138Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T19:57:21.200Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T19:57:36.137Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T19:57:51.142Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T19:58:06.144Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T19:58:21.160Z
sensor.heliotherm_heatpump_cop,3.4,2025-11-27T19:58:36.147Z
sensor.heliotherm_heatpump_cop,3.6,2025-11-27T19:58:51.147Z
sensor.heliotherm_heatpump_cop,3.5,2025-11-27T19:59:51.152Z